DICOM Correction Item

Correction Number CP- 562	
Log Summary: Correct TID 4020	
Type of Modification	Name of Standard
Correction	PS 3.16-2004
Rationale for Correction: The Value Multiplicity of row 4 (Image View Modifier) of TID 4020 CAD Image Library Entry was incorrectly assigned as "1". The source of the value of this content item is the image attribute View Modifier Code Sequence (0054,0222), which may have zero or more sequence items. Therefore, the Value Multiplicity of the Image View Modifier content item should be "1-n".	
Sections of documents affected PS 3.16 – TID 4020	
Correction Wording: See below	

Update row 4 of TID 4020 as follows:

TID 4020
CAD IMAGE LIBRARY ENTRY
Type: Non-Extensible

	NL	Rel with Parent	VT	Concept Name	VM	Req Type	Condition	Value Set Constraint
1			IMAGE		1	M		
2	>	HAS ACQ CONTEXT	CODE	EV(111027, DCM, "Image Laterality")	1	MC	Shall be present if (0020,0062) is in the Image Instance	$ImageLaterality
3	>	HAS ACQ CONTEXT	CODE	EV (111031, DCM, "Image View")	1	MC	Shall be present if (0054,0220) is in the Image Instance	$ImageView
4	>>	HAS CONCEPT MOD	CODE	EV (111032, DCM, "Image View Modifier")	1**-n**	MC	Shall be present if (0054,0222) is in the Image Instance	$ImageViewMod