

DICOM Correction Item

Correction Number		CP- 168	
Log Summary: Non-Encoded Failure Status Code- Add No such Action Code			
Type of Modification	Name of Standard		
Clarification	PS 3.7		
<p>Rationale for Correction</p> <p>Section C.10.1.4.1.10 list the status: " —no such action: the action type specified was not supported." But section C.5 Failure Status Classes does not define an encoding for this status. It is proposed to add this status to the list in Annex C.</p>			
<p>Sections of documents affected</p> <p>In PS 3.7, Section C.10.1.4.1.10</p>			
<p>Correction Wording:</p> <p>In Section C, Status Type Encoding, add to the list of status: Section 5.24 No such action type</p>			

C.5.24 No such action type

Status Field	Tag	VR	VM	Description of Field
Affected SOP Class UID	(0000,0002)	UI	1	This optional field contains the SOP Class UID for which the event type does not exist.
Status	(0000,0900)	US	1	Confirmation status of the operation. The value of this required field shall be set to 0123H.
Action Type ID	(0000,1008)	US	1	This optional field contains the ID of the Action Type which does not exist.