

DICOM Correction Item

Correction Number	CP-1113
Log Summary:	Correct Lead III Code
Type of Modification	Name of Standard
Modification	PS 3.16-2011
Rationale for Correction:	
Wrong code in TID 3001	
Sections of documents affected	
PS 3.16 Annex B	
Correction Wording:	

Context ID 3001
ECG Leads

Type: Extensible Version: ~~20080927~~yyyymmdd

Coding Scheme	Code Value	Code Meaning	IEEE 11073 MDC Equivalent Reference ID (informative)
...			
MDC	2: 361	Lead III	MDC_ECG_LEAD_III
...			