

## DICOM Correction Proposal

STATUS	Final Text
Date of Last Update	2012/06/05
Person Assigned	Björn Nolte (bjoern.nolte@siemens.com)
Submitter Name	Björn Nolte (bjoern.nolte@siemens.com)
Submission Date	2011/09/06

Correction Number	CP- 1192
Log Summary:	Typo error – tag mismatch between RT Beams Delivery instruction module and dictionary
Name of Standard	PS 3.3 - 2011
Rationale for Correction:	<p>Typo error in the TAGs for Lossy Image Compression Method within <b>Table C.8.8.29-1 RT BEAMS DELIVERY INSTRUCTION MODULE ATTRIBUTES</b>.</p> <p>&gt;Table Top Vertical Adjusted Position      (<del>0074,0126</del>) to (0074,1026)          &gt;Table Top Longitudinal Adjusted Position   (<del>0074,0127</del>) to (0074,1027)          &gt;Table Top Lateral Adjusted Position        (<del>0074,0128</del>) to (0074,1028)</p>
Correction Wording:	

<b>Modify TAGs in Table C.8.8.29-1 RT BEAMS DELIVERY INSTRUCTION MODULE ATTRIBUTES</b>
----------------------------------------------------------------------------------------

...

>Table Top Vertical Adjusted Position	<del>(0074,0126)</del> <b><u>(0074,1026)</u></b>	2	Adjusted Table Top Vertical position in the IEC TABLE TOP coordinate system in mm for patient setup. See C.8.8.29.2.
>Table Top Longitudinal Adjusted Position	<del>(0074,0127)</del> <b><u>(0074,1027)</u></b>	2	Adjusted Table Top Longitudinal position in the IEC TABLE TOP coordinate system in mm for patient setup. See C.8.8.29.2.
>Table Top Lateral Adjusted Position	<del>(0074,0128)</del> <b><u>(0074,1028)</u></b>	2	Adjusted Table Top Lateral position in the IEC TABLE TOP coordinate system in mm for patient setup. See C.8.8.29.2.

...