

DICOM Correction Item

Correction Number		CP- 168	
Log Summary: Non-Encoded Failure Status Code- Add No such Action Code			
Type of Modification	Name of Standard		
Clarification	PS 3.7-1999		
<p>Rationale for Correction</p> <p>Section C.10.1.4.1.10 list the status: " —no such action: the action type specified was not supported."</p> <p>But section C.5 Failure Status Classes does not define an encoding for this status. It is proposed to add this status to the list in Annex C.</p>			
<p>Sections of documents affected</p> <p>In PS 3.7, Section C.10.1.4.1.10</p>			
<p>Correction Wording:</p> <p>In Section C, Status Type Encoding, add to the list of status: Section 5.24 No such action type</p>			

C.5.24 No such action type

Status Field	Tag	VR	VM	Description of Field
Affected SOP Class UID	(0000,0002)	UI	1	This optional field contains the SOP Class UID for which the action type does not exist.
Status	(0000,0900)	US	1	Confirmation status of the operation. The value of this required field shall be set to 0123H.
Action Type ID	(0000,1008)	US	1	This optional field contains the ID of the Action Type which does not exist.