

2

DICOM Correction Item

| | | |
|---|------------------|--------|
| Correction Number | | CP-354 |
| Log Summary: Adjust the Printer Buffer Status name to 16 characters. | | |
| Type of Modification | Name of Standard | |
| Correct Value | PS 3.3 2003 | |
| Rationale for Correction | | |
| A VR of CS may contain a maximum of 16 characters. "PRINTER BUFFER FULL" exceeds the limit. | | |
| Sections of documents affected | | |
| PS 3.3 Section: C13.9.1 | | |
| Correction Wording: | | |

4

In PS 3.3 shorten the Defined Term to comply with the attribute VR of CS

C.13.9.1 Printer Status Info and Execution Status Info

6

Additional Defined Terms for Printer Status Info (2110,0020) and Execution Status Info (2100,0030) are:

| | |
|---|--|
| ... | |
| PRINTER BUFFER PRINT BUFF FULL | The Printer 's buffer capacity is full. The printer is unable to accept new images in this state. The printer will correct this without user intervention. The SCU should retry later. |
| ... | |

8