

1	STATUS	Letter Ballot
2	Date of Last Update	2014/09/08
3	Person Assigned	David Clunie
4		mailto:dclunie@dclunie.com
5	Submitter Name	David Clunie
6		mailto:dclunie@dclunie.com
7	Submission Date	2014/01/27

8	Correction Number CP-1369	
9	Log Summary: Relax device identifier constraint in x-ray irradiation event per CP 1065 undone by CP 1077	
10	Name of Standard	
11	PS3.16 2014b	
12	Rationale for Correction:	
13	CP 1065 made the TID 1021 inclusion within TID 10003 conditional upon it being different from the observer context rather than	
14	mandatory; CP 1077 that refactored the TID 10003 into separate sub-templates inadvertently undid this by making it mandatory	
15	again.	
16	Restore the 1065 condition on the inclusion of TID 1021 in what is now TID 10003b.	
17	Correction Wording:	

Amend DICOM PS3.16 - Content Mapping Resource - Structured Reporting Templates as follows:

TID 1410

Table TID 10003b. Irradiation Event X-Ray Source Data

	NL	Rel with Parent	VT	Concept Name	VM	Req Type	Condition	Value Set Constraint
...		
27			INCLUDE	DTID 1021 Device Participant	1	MC	<u>Required if the irradiating device is not the recording device.</u>	\$DeviceProcedureRole = EV (113859, DCM, "Irradiating Device")