

DICOM Correction Item

Correction Number	CP-43
Log Summary: Double occurrence of LUT Number in Module	
Type of Modification Errata	Name of Standard PS 3.3 - 1993
Rationale for Correction Double occurrence of LUT Number Attribute in same table	
Sections of document affected Table C.11-3, LUT Identification Module attributes	
Correction Wording remove last row of table C.11-3 "LUT Identification module attributes"	