

DICOM Correction Item

Correction Number	CP-524
Log Summary:	Change "procedure" to "analysis" in QVA
Type of Modification	Name of Standard
Addition	PS 3.16-2004
Rationale for Correction:	
<p>WG8 had decided to use (111004, DCM, "Analysis Performed"), rather than (121058, DCM, "Procedure Reported"), for identifying the lower level analyses in the Quantitative Ventriculography SR. This is to be consistent with use in Mammo and Chest CAD.</p> <p>This decision was not carried through into the Sup76 Ballot and Final Text.</p>	
Sections of documents affected	
PS 3.16 Annex A	
Correction Wording:	
Modify PS3.16 Annex A	

TID 3208
FRAME-TO-FRAME RESULT
 Type: Extensible

NL	Rel with Parent	VT	Concept Name	VM	Req Type	Condition	Value Set Constraint
1		CONTAINER	EV (121070, DCM, "Findings")	1	M		
2	> HAS CONCEPT MOD	CODE	EV (121058, DCM, "Procedure Reported") EV (111004, DCM, "Analysis Performed")	1	M		EV (122499, DCM, "Frame to Frame Analysis")
...							

TID 3209
CENTERLINE WALL MOTION
 Type: Extensible

NL	Rel with Parent	VT	Concept Name	VM	Req Type	Condition	Value Set Constraint
1		CONTAINER	EV (121070, DCM, "Findings")	1	M		
2	> HAS CONCEPT MOD	CODE	EV (121058, DCM, "Procedure Reported") EV (111004, DCM, "Analysis Performed")	1	M		EV (122449, DCM, "Centerline Wall Motion Analysis")
...							

TID 3210
RADIAL BASED WALL MOTION
 Type: Extensible

