

### DICOM Correction Item

Correction Number CP- 575	
Log Summary: Clarify use of Multiplexed Audio for MPEG	
Type of Modification Addition	Name of Standard Part 3
Rationale for Correction: The type is wrong for those cases where no audio has been encoded. It is still possible that no audio data was encoded for an IOD using the MPEG transfer syntax. For those cases the audio sequence must be present but may be empty.	
Sections of documents affected PS 3.3 C.7.6.5.1.3	
Correction Wording:	

*Change type of Multiplexed Audio Channels Description Code Sequence*

...			
Multiplexed Audio Channels Description Code Sequence	(003A,0300)	<del>2C1C</del>	Description of any multiplexed audio channels. See Section C.7.6.5.1.3. Required if the Transfer Syntax used to encode the multi-frame image contains multiplexed (interleaved) audio channels, such as is possible with MPEG2. <b><u>Zero or more items may be present in this sequence.</u></b>

*Add note to the end of section C.7.6.5.1.3*

**Note:** If no audio was recorded, the Multiplexed Audio Channels Description Code Sequence (003A,0300) will be present and contain no sequence items.