

DICOM Correction Item

Correction Number		CP-608
Log Summary: Remove duplicate registry entry for data element (0018,9022) Blood Signal Nulling		
Type of Modification	Name of Standard	
Correction	PS 3.6 2004	
Rationale for Correction.		
PS 3.6 Section 6 Registry of DICOM data elements contains two entries for element (0018,9022) Blood Signal Nulling.		
Sections of documents affected		
PS 3.6 Section 6		
Correction Wording:		

In PS3.6, Section 6, remove second entry for (0018,9022) Blood Signal Nulling:

Tag	Name	VR	VM
(0018,9021)	T2 Preparation	CS	1
(0018,9022)	Blood Signal Nulling	CS	1
(0018,9024)	Saturation Recovery	CS	1
(0018,9025)	Spectrally Selected Suppression	CS	1
(0018,9026)	Spectrally Selected Excitation	CS	1
(0018,9027)	Spatial Pre-saturation	CS	1
(0018,9028)	Tagging	CS	1
(0018,9029)	Oversampling Phase	CS	1
(0018,9022)	Blood Signal Nulling	CS	1
(0018,9030)	Tag Spacing First Dimension	FD	1