

DICOM Correction Item

Correction Number		CP-669
Log Summary: Correct content item conditions in TID 5202		
Type of Modification	Name of Standard	
Addition	PS 3.16 2004	
Rationale for Correction		
<p>Template 5202 improperly specifies conditions on concept modifiers for the Measurement Group. UC (User-Option, Conditional) constraints typically define the conditions when the content item shall NOT be present; in all other conditions it MAY be present at the option of the producing application.</p> <p>WG12 has determined that these conditions are unnecessary.</p>		
Sections of documents affected		
PS 3.16 Annex B		
Correction Wording:		

TID 5202
ECHO SECTION
 Type: Extensible

NL	Rel with Parent	VT	Concept Name	VM	Req Type	Condition	Value Set Constraint
1		CONTAINER	EV (121070, DCM, "Findings")	1	M		
2	>	HAS CONCEPT MOD	CODE EV (G-C0E3, SRT, "Finding Site")	1	M		\$SectionSubject
3	>	CONTAINS	CONTAINER DT (125007, DCM, "Measurement Group")	1-n	M		
4	>>	HAS CONCEPT MOD	CODE EV (G-0373, SRT, "Image Mode")	1	UC	IFF measurements are grouped by image mode	BCID (12224) Ultrasound Image Modes
5	>>	HAS CONCEPT MOD	CODE DT (125203,DCM,"Acquisition Protocol")	1	UC	IF Row 4 is not present	
6	>>	CONTAINS	INCLUDE DTID (5203) Echo Measurement	1-n	M		\$Measurement = \$MeasType \$Method=CID (12227) Echocardiography Measurement Method