

DICOM Correction Item

Correction Number CP-967	
Log Summary: Correct CID 3232	
Type of Modification Modification	Name of Standard PS 3.16-2008 + Sup128
Rationale for Correction: The American Society of Nuclear Cardiology is revising their recommendations on stress test reporting and harmonizing with Sup128. This review has identified an incorrect term and some missing terms from CID 3232.	
Sections of documents affected PS 3.16 Annex B CID 3232	
Correction Wording:	

CID 3232 ST Segment Location

**Context ID 3232
 ST Segment Location**

Type: Extensible Version: 2008092720091021

Coding Scheme Designator	Code Value	Code Meaning
SRT	T-3260A	Left ventricle anterior segment
SRT	T-3260C	Left ventricle inferior segment
SRT	T-3260D	Left ventricle lateral segment
SRT	T-32615	Left ventricle posterior segment
<u>SRT</u>	<u>T-3260B</u>	<u>Left ventricle septal segment</u>
<u>SRT</u>	<u>T-32602</u>	<u>Left ventricle apical segment</u>