

DICOM Correction Proposal

STATUS	Letter Ballot
Date of Last Update	2014/09/08
Person Assigned	Bas Revet (bas.revet@philips.com)
Submitter Name	Heinz Blendinger (heinz.blendinger@siemens.com)
Submission Date	2014/02/14

Correction Number	CP-1382
Log Summary:	Correct element number in reference to SOP Instance UID
Name of Standard	PS 3 2013
Rationale for Correction:	Incorrect element number used in reference to SOP Instance UID
Correction Wording:	

Correct element number in Part 3 (2011) section C.7.6.16.2.2.4 Concatenations and Stacks

...

- Number of Frames (0028,0008)
- Concatenation Frame Offset Number (0020,9228)
- In-concatenation Number (0020,9162)
- SOP Instance UID (0008,00**4618**)
- Instance Creation Time (0008,0013)

...