

### DICOM Correction Item

2

|  |  |                  |  |
|--|--|------------------|--|
| Correction Number  |  | CP-203           |  |
| Log Summary: Add Defined Terms for Printer Status Info (2110,0020).  |  |                  |  |
| Type of Modification: Addition   |  | Name of Standard |  |
|  |  | PS 3.3-1999      |  |
| <p>Rationale for Correction:</p> <p>The Printer Status Info and Execution Status Info is missing the following events:</p> <p>“Printer Busy” – Printer is not ready during non-initialization. This is a complementary status to the defined status “PRINTER INIT”.</p> <p>“Printer Buffer Full” – The Printer Spooling storage device reached his capacity usage.</p> |  |                  |  |
| <p>Sections of document affected:</p> <p>PS 3.3-1999, Section C.13.9.1</p>   |  |                  |  |
| <p>Correction Wording:</p> <p>See below.</p>   |  |                  |  |

4

*Add the following entries to Section C.13.9.1 – Printer Status Info in PS 3.3-1999*

|                     |  |
|---------------------|--|
| PRINTER BUSY        | Printer is not available at this time, but should become ready without user intervention. This is to handle non-initialization instances.  |
| PRINTER BUFFER FULL | The Printer 's buffer capacity is full. The printer is unable to accept new images in this state. The printer will correct this without user intervention. The SCU should retry later. |

6