

### DICOM Correction Item

Correction Number CP-835	
Log Summary: Clarify VM of Transducer Data	
Type of Modification Clarification	Name of Standard PS 3.6 - 2008
Rationale for Correction: PS 3.6 specifies the VM=3 for Transducer Data (0018,5010), requiring many implementations to store two delimiters in the Value Field of Data Element.	
Sections of documents affected PS 3.6	
Correction Wording:	

*In PS 3.6, Modify Section 6 at the following tag:*

Tag	Name	VR	VM
(0018,5010)	Transducer Data	LO	<u>1-n</u> <del>3</del>